

ODA V1.1 changes from V1.0

5_15_2013

agdr

- ❖ Updated the BOM and did a re-numbering of the parts on the PCB.
- ❖ Relay suppression upgraded from just a diode across the coil to diode + 14Vdc zener. Faster closure and longer relay life. See Tyco application note.
- ❖ Relay mosfets now correctly marked as *any* 2N7000 since gates are voltage divider limited to 17.5Vdc. Cuts the cost by \$0.40 each over special 30V gate units and higher availability of the part.
- ❖ Relay timing capacitor value increased to 4.7uF from 2.2uF to get (longer) 4 seconds of turn-on delay. I forgot the previous values were from an O2 mod that attached *after* the power management circuit and its added delay.
- ❖ Relay control circuit layout improved a bit and modified to add the zener and bigger timing capacitor.
- ❖ R70 in relay control changed to SMD to improve layout.
- ❖ Pre-regulator protection diodes D3 and D4 reversed on schematic and layout – they were bypassing the pre-regulators.
- ❖ Build instructions note added about how to orient tombstoned diodes.
- ❖ Voltage regulator resistors upgraded to 0.1% SMD from 1% through-hole for more voltage accuracy. 0.1% standard values allow for exact +/-17.0V high rail instead of +/-16.9Vdc. Several resistors changed from through-hole to SMD in the power regulator section.
- ❖ JP4, JP7, JP8, the ground V+ and V- test and tap-off holes, changed from 2 hole to 4 hole to allow more power supply tap-offs for an accessory PCB.
- ❖ Added more PCB trace metal around JP4, JP7, and JP8 to handle full power rail load current even if nothing is soldered into the PCB holes to bridge the traces.
- ❖ Various layout changes to improve the layout in the power supply section.
- ❖ R21 in gain stage now SMD to better clear the IC.
- ❖ Gain stage feedback resistor R22, R23 and R24 changed to SMD to increase accuracy to 0.1%. All the gain switch resistors are now 0.1% SMD. Will help with accurate channel to channel gain matching.
- ❖ Output buffer power supply bypassing changed from 0.01uF MLCC 0805 SMD caps rail-to-rail on each chip to 0.22uF film caps wired as rail-to-ground and rail-to-rail on each bank. 0.001uF axial MLCC COG / NPO capacitors added to the BOM as optional HF bypass that can be soldered right

across the film cap leads on the bottom of the PCB. Chip manufacturers often recommend a parallel bypass combo of an electrolytic (the 390uF caps in this case), a film cap (the 0.22uF), and a small value ceramic like these 1000pF units to bypass all oscillation frequencies.

- ❖ Output parallel balance resistors changed from 1R to 3.32R to maintain the O2 amps' total 0.5R output impedance. Allows the chips to idle cooler by passing less balancing current.
- ❖ Both 3.5mm input jack series 274R resistors are now 0.1% surface mount to match. Previously one was SMD and the other was 1% through hole.
- ❖ A few layout improvements in the DC servo section.
- ❖ Mouser had 10uF C41 in the clipping circuit listed as 5mm lead spacing when it is actually 2mm. Fixed this on the layout.
- ❖ Angled Q1 and R39 on the layout to allow more spacing between RCA jack signal lines, preventing crosstalk problems.
- ❖ Changed the clipping LED series current limit resistor to 15K from 3.6K
- ❖ Added the X2Y EMI suppression capacitor back to the 3.5mm input that was removed for space reasons when the input selector switch was added.