



## LINE 2 - REPAIR MANUAL

*BB PAGES*

SONIC FRONTIERS warranty repair work shall be performed only by qualified electronics technicians. Work done by non-authorized SONIC FRONTIERS service locations and/or dealers is not covered under the SONIC FRONTIERS warranty. Damage caused by service attempted by one other than our authorized service bureaus is not covered under the warranty.

Please read these instructions before attempting any service work. They are intended to aid the electronics technician in making the proper diagnosis in repairing the Line 2 preamplifier.

### **Normal Operation**

The following points have been found to be the most frequent areas of concern from customers, **no fault exists in the Line 2 in each case.**

1. Some hiss in speakers.

- The Line 2 incorporates 6 vacuum tubes and will inherently make more hiss noise than a solid state product. Typical noise output is no more than  $120\mu V$  per phase with the volume control fully counter-clockwise.
- Sensitive amplifiers and sensitive speakers will reveal this hiss more readily than average sensitivity amplifiers and speakers, example: an amplifier with an input sensitivity of  $0.775V_{rms}$  and speakers with a sensitivity of 90dB SPL @1W, 1m anechoic would be considered moderately sensitive.

All components listed in the text will have the same designation for both channels but with an 'L' prefix for Left channel components. For this reason, all parts will be referred to by Left channel only. Example: resistors LR43 and R43; the resistor LR43 is found in the Left channel and R43 is in the Right channel.

### **Filament Supply Voltages**

1. Filament voltage should be measured across pins 4 and 5 of the following tubes: LV1 and LV3. A reading of 6.0Vdc to 6.3Vdc is acceptable, any voltages higher or lower must be

2. If one channel has no filament voltage present, check the bridge rectifier for the filament section, LBR1 in the Power Supply chassis. Replace if needed and place a heat sink on both the filament bridge rectifier devices; this will improve heat dissipation.

3. If only tubes LV1 and LV2 are not lighting, check regulator LIC2 in the Power Supply chassis. If only tubes LV3 and LV4 are not lighting, check regulator LIC1.

### **High Voltage Supplies**

Note: The following voltages are measured referenced to chassis ground or an audio ground (RCA jack sleeve is sufficient).

1. With the Power supply switched to ON and the STANDBY position, check the voltages

Power Supply	Mode of Operation		
Pin Number	Standby	Operate	Muted


**SONIC FRONTIERS**  
 INCORPORATED

1	6.1	5.4	
2	-12.1	-12.1	
3	18.3	18	
4	5.1	1.5	5.3
5	-0.1	-123	
6	0	0	
7	10.9	0.1	
8	9.9	9.2	
9	-4.7	270	
10	-1	146	
11	0.2	1.5	5.3
12	6.15	6.15	
13	6.15	6.15	
14	6.15	6.15	
15	0	0	
16	0	0	

Front View




Figure 1

2. Place a voltmeter probe on the tab (drain) of Q3 or LQ3 and switch the Power supply to the OPERATE position. The voltage should ramp up to approximately 285Vdc  $\pm 10$ V within 40 seconds. If the voltage goes immediately to 300Vdc after switching to OPERATE, there is a problem in the first High Voltage regulation stages at LQ2 and LQ5. Check these components as well as each string of Zener diodes from LZD1 to LZD15. (If the circuit board is a REV.0 board, refer to Ed's Tech Notes - Power Supply Update for the SFL-2).
3. Measure the voltage on the tab of LQ6, the voltage should be approximately 155Vdc  $\pm 10$ V.
4. Measure the voltage at the source pin of LQ3, the voltage should be exactly 10Vdc less than the voltage measured on the tab. If this voltage is not 10V less, there is a problem in the buffer regulator. Check diodes LZD10 and D4-D6. Check LQ3 and replace LIC1 if necessary.
5. Measure the voltage on the source of LQ6, the voltage should be exactly 10Vdc less than the voltage measured on the tab. If this voltage is not 10V less, check LZD16, LD10 and LD14. Check LQ6 and replace LIC2 if necessary.


**Noise** (Example case for noise in Left channel)



**SONIC FRONTIERS**  
INCORPORATED

1. Reverse tubes LV1 and V1. If the noise is no longer in the Left channel but now in the Right channel, the noise problem was noisy tube LV1. If the noise remained in the Left channel, switch tubes LV2 and V2. If the noise is no longer in the Left channel but now in the Right channel, the noise problem was noisy tube LV2.

2. If after reversing tubes LV1 and V1 or LV2 and V2 did not find the noise, listen to the output of the Line 2 through the unbalanced outputs only for this next test. Switch between  $0^\circ$  Phase and  $180^\circ$  Phase, if the noise is only present in the  $0^\circ$  Phase, replace resistor LR. If the noise is only in the  $180^\circ$  Phase, replace resistor LR. If the noise is in both Phases of the output replace resistors LR and LR.




NUMBERS 1 TO 16 ARE O/P FROM LINE 2 POWER SUPPLY FOR MAIN PCB LINE 2

ZL2P2Z

SOHIC IRONHILL INC.

ZL2P2Z.SCH

DESIGNER: ZDENKO ZIVKOVIC  
DATE: May 1996



+165V UNR.FOR -128V SUPPLY(FLOATING)

-165V UNR.FOR -128V SUPPLY(FLOATING)

SR18

SR23

SR22

+330V UNR.FOR +270V

SUPPLY

100R

+270V REGULATOR

SR18

SR10

IN4148

SR12

150R

IN4148

SR14

150R

IN4148

SR15

1M82

SR16

330K 2W

SR17

2.2uF 400V

SC17

7.2uF 400V

SC18

2.2uF 400V

SC19

15uF 400V

SC20

15uF 400V

SC21

15uF 250V

SC22

15uF 250V

SC23

15uF 250V

SC24

15uF 250V

-128V REGULATOR

SR18

SR07

IN4007

SR09

150R

IN4149

SR08

2TR4

SR05

2SA1142

SR06

SR07

SR08

SR09

SR10

150K 2W

SR11

SR12

SR13

SR14

SR15

SR16

SR17

SR18

SR19

SR20

SR21

SR22

SR23

SR24

SR25

ZZLP221

NUMBERS 1 TO 16 ARE O/P FROM LINE 2 POWER SUPPLY FOR MAIN PCB LINE 2

PSGND

+270VR+L

9

-128VR+L

5

SONIC FRONTIERS INC.

LINE 2 POWER SUPPLY(PART 2) SKU 56744.10

REV 0

SIZE


A 0 SIGN R 20 NOV 1996

DATUM NOV 1996

1 SHEET

04111 FOR 'ON' NINE R. WILHELM 05

### III Headphone amplifier




SONIC FRONTIERS INC.

HEADROOM-Headphone amplifier LINE 1.2.3  
S101 A REDESIGNER: ZDENKO ZIVKOVIC DATE: NOV. 1996 SHEET 01

C11.15 IN PTC 7KU 56.792.10  
ARE 150pf + 220pF(370pf)


TP 1/10°

REV






TAPE BUFFER

LEFT CHANNEL SHOWN




## SIGNAL SWITCHING DIAGRAM







LEFT AND RIGHT CHANNEL


PART OF MAIN PCB






Duplicate this for Right Channel







KONIC FRONTIERS INC.		REV
LINE 2 CONNECTIONS		
617	BUDIMIR ZIVKOVIĆ	
A		
DATE	NOV 1996	



卷之三




TEST	TEST	TEST	TEST	TEST
TEST	TEST	TEST	TEST	TEST
BALANCE EIGHT	420	420	420	420
BALANCE EIGHT	421	421	421	421
CHANGE	422	422	422	422
CHANGE	423	423	423	423
STANDBY	424	424	424	424
STANDBY	425	425	425	425
BAL1	426	426	426	426
BAL1	427	427	427	427
MUTE	428	428	428	428
MUTE	429	429	429	429



E.C.N.# : PRODUCT :

## ENGINEERING CHANGE NOTICE

<b>PRODUCT(S) AFFECTED</b> <u>Change or modification</u> Temporary ( )      Permanent ( )		<b>DATE OF ISSUE:</b>  <b>ISSUED BY :</b>  <b>APPROVED BY :</b>
<b>PURPOSE OF CHANGE(S):</b> <i>Line 2 Headphone Hum Reduction</i>		
		
<b>DESCRIPTION OF CHANGE(S):</b>		
<b>PART(S) AFFECTED :</b>	<b>PART #</b>	<b>LOCATION:</b>
<b>ADD:</b>	<b>PART #</b>	<b>LOCATION:</b>
<b>MODIFICATION DIAGRAM:</b> See attached sheet		C.C I. Driver T. Nguyen A. Jez K. Wilk N. Platsis
		<b>CONFIRMED :</b>

