

The C2238B (70415030) and A968B (70415031) predrivers have been replaced with 15032 (70415032) and 15033 (70415033) higher-current devices. Three resistor changes per drive board are required to utilize these parts. Note any unit in for repair should have the new parts installed to improve reliability.

Channel A shown, Channel B Similar.