

didn't have buck
before on tpa3116 amps
added it cus voltage drop is from -
30v instead of 24v.
didn't seem to add noise

