


9-20-2021



NOTE: Rdamp and Cdamp installed across RCA input connectors' signal and shield tabs.