

0,0

## X AXIS

1500,340



A



5450,340

B

340,1500



C

6610,1500



D

All measurements are X then Y  
Measurements in Thousands of an inch from Origin 0,0  
All Holes 10/32 UNF x 400 thou

All drilling must be measured from Origin 0,0  
No other machining required, just drilling & tapping

## Y AXIS

340,6050



E

6610,6050



F

1500,7550



G



5450,7550

H