





Due to interference of MOSI, adding one 22pF shunt capacitor to GND fixes problems writing to the DAC.


#### +5V SELECTOR




#### +5V Regulator




#### Expansion Socket



#### Test Socket



#### Expansion Module



#### Power Supply

