



COPPER SHIELDING  
FOR OSCILLATORS

CONNECT / SOLDER  
THE SHIELD TO THESE GND PADS