

Modification L1210 servo board – "No disc" playability issue.

Components side of the L1210 servo board.
Location near the mechanism flex connector.

R952 old value: 12k ohms
R952 new value: 22k ohms

