


1		2		3		4		
A	Page 00: Cover page (this page)			<div>DAC 200_M</div> <div>VER3.0</div>				A
	Page 01: DIR9001.sch							
	Page 02: TDA1541.sch							
	Page 03: LPF.sch							
	Page 04: Power.sch							
B	Page 05: TDA1541_VER6.0.pcb							B
C								C
D								D
1		2		3		4		

Title			
Cover			
Size	Number		Revision
A4			2.0
Date:	2016-3-2		Sheet of 0 of 4
File:	E:\work\100_Cover.SchDoc		Drawn By: DrawnBy: Mark Liang



Page 00: Cover page (this page)
Page 01: DIR9001.sch
Page 02: TDA1541.sch
Page 03: LPF.sch
Page 04: Power.sch
Page 05: TDA1541_VER6.0.pcb

Ver2.0
1. Changer relay driver PNP transister to NPN
2. DIR9001 FILT PIN Capacitor value is wrong at VER1.0, so change .
3. Optical reciever connect to bus buffer direct.
2010/03/09
Ver3.0
1. Add one resister to COXA input pin. (DIR9001.Doc) ADD one resister(75R) to U4 Pin6 & Pin7
2. Add one resister to relay driver input pin. (LPF.Doc) ADD one resister(2K) to Q2 pin1 & pin2
3. Del P5/P6 (DIR9001.Doc)
4. digital part power source from VCC15. (DIR9001.Doc)
5. L1,L2,D3,Q1,Q2 footprint change to DIP
6. R17 change to CAP.
7.DEL U5,C10,R13
8. DEL R18(33R)
2010/10/14
Ver4.0
1. all components footprint will change to DIP
2. DEL relay function
3. change power mode
4. ADD RCA socket output
5. Fix OPT noise
2011/03/27
Ver5.0
1. Fix Diode direction issue
2. PCB will bigger
Ver6.0
1. change +-5V, Power get from +-8V
2. PCB will bigger







Title			
Cover			
Size	Number		Revision
A4			2.0
Date:	2016-3-2	Sheet of	0 of 4
File:	E:\work\...\00_Cover.SchDoc	Drawn By:	DrawnBy: Mark Liang



Title		
Size	Number	Revision
A4		
Date:	2016-3-2	Sheet of
File:	E:\work\..02_TDA1541.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	2016-3-2	Sheet of
File:	E:\work\...\03_LPF.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	2016-3-2	Sheet of
File:	E:\work\...\04_Power.SchDoc	Drawn By: