

4 ohm load

S/C 4/6, 5/7

Load 5/7 and 4/6

4Ω 0

8 ohm load

Connect across

8 and 6

8Ω 0

16 ohm load

S/C 4/7

Connect across

5 and 6

16Ω 0

OUTPUT TRANSFORMER HOOK-UP FOR FERGUSON 603 ONLY.

Mike

2013

PrintFreeGraphPaper.com