
Potentiometer frequency
SL→LL
Speaker level to line level conversion
Speaker R
Speaker L
Line Level R
Line Level L
BUF
Input buffers
Line Level R
Line Level L
SUM
L+R summing
SUM L+R
LP
12/24 dB LR low pass
SUM L+R
BUF
Input buffer
LFE
LFE
REL
Relais NO=LFE
EQ
3x EQ section Peak/Notch
LT
Linkwitz transform
Phase
0-180° phase control
BUF
Output buffer
LFE SW
LFE signal induced switch
Relais release switch
Switch signal
Potentiometer phase
Potentiometer volume