


sted types. All
s not within dotted
1. All capacitors
ls except those
arads) and those
as a decimal point
arads = 1500
esistors, K =
ohms. Thus 3M3 =