

For first setup do not fix/assemble Red marked components.

- for DC Offset check point
- for freq. measure point using DSO/CRO