
Mount Nixie Tubes on Other Side
U4
HV_PSU
P1
P2
Phoenix
Engineering
U2
X1
U3
U1
Test
TTL
RS232