



The audio signal arrives 3400\1 and 3401\5 at the same time this is correct, yes?

3401 there is a 100k resistor built-in to this pot; on the line drawing shows the lower half from connections 5 to 6 filled in what does this indicate; that the wiper has no contact in this area?

And that being related to the Sensitive Control moving off 4 to 5 or 5 to 6 has an effect on the audio signal?

6 is connected to ground, and 4 is just a connection going nowhere, it's only purpose that I can see is providing a test point, to test this 100k you would then think to test this resistor, connect to 4 and 6?