

.include BC550.lib
 .include BC560.lib

Copyright 2008 - Russ White

```
.options plotwinsize = 0
.ac dec 24 1k 1g
.tran 0 2m 10u 1E-7
.four (F) V(OUT+,OUT-)
.params F=20K V=1 SINE(0 (V) (F) 100u) SINE(0 (V) (F) 100u 0 180)
```

.step param F list 1K 5K 10K 20K

