


SpeakerCraft BB2125 Power Amp

Burnt looking resistors on main board R10 & R1 (R10 measures 14ohms; R1 measures infinity)



Damaged resistors at speaker output

