


Notes
 ① TTL - Flush to board
 $\frac{5}{16}'' \times \frac{5}{16}''$

② TORX
 $\frac{7}{16}''$ wide, $\frac{1}{16}''$ above board; $\frac{11}{32}''$ high
 screw hole, $\frac{5}{8}''$ above board

③ BNC
 $\frac{9}{32}''$ above board; $\frac{1}{2}'' \phi$



$\frac{1}{4} \frac{7}{16}$