



Adjust P2/ R7 and P3/ R13 to 180 Ohm
 ground gate of T1-T4
 lift point A from ground
 adjust A to ground to 0V
 wire the circuit back
 adjust DC offset after T7 / T8 to + - 5mV with P2
 fine adjust Offset with P4
 OP1, OP2, OP3 decoupled with 220uF, 1u, 10n
 T1 / T2 = 2SK170BL
 T3 / T4 = 2SJ74
 T5 / T8 = BF446A
 T7 / T8 : selected for Hfe