

## Excel Export Setup File Parameters

Run Name: 8581- SO2100-2-XT4117-11.2896M

Path: \\Srv2\Production\Thermal Run Data\

Print: All Operator:

Run Start: 16-Mar-2015 3:14 pm

S&A W2200 Rev: 5.75 Report: 2.20

Ref F: F @ 25.00°C (Actual)

Run Finish: 16-Mar-2015 4:30 pm

Setup File:

\\Srv2\Production\QCC for all\FABO\XT4117.qcc

CL: 16.5pF

Crystal ID	FL ±5 ppm	RR Ohms	C0 pF	C1 fF	Q >100 k	F/T ±3 ppm	IT1 °C	ANGL
B004	-1.0	9.0	2.59	11.960	132	1.1	25.6	0.87
B006	-2.6	8.0	2.61	12.253	144	0.9	26.5	1.01
B008	-4.1	9.5	2.63	11.538	129	0.7	27.7	0.39
B013	-3.0	8.4	2.67	11.719	144	1.2	26.3	0.87
B014	-3.7	8.9	2.58	11.926	133	-0.9	28.1	0.57
B015	-3.4	8.6	2.68	12.554	131	-1.9	29.2	1.29
B016	-5.4	9.9	2.65	11.531	123	0.7	27.5	0.56
B017	-1.5	7.8	2.56	11.315	159	-1.1	28.3	0.72
B020	-1.5	7.3	2.72	12.712	152	1.4	25.6	1.23
B022	-1.3	9.1	2.67	11.842	130	0.9	27.2	0.70
B023	-1.5	7.9	2.61	11.437	156	0.8	27.9	0.58
B024	-0.5	8.8	2.68	12.101	133	1.0	30.1	0.92
B027	-2.1	8.8	2.59	11.388	141	-0.9	27.3	0.42
B029	-2.5	9.9	2.67	11.630	123	0.9	27.2	0.82
B030	-1.3	8.2	2.61	12.010	143	1.1	25.2	0.92
B031	-1.7	9.0	2.62	11.420	138	-1.0	29.5	0.78
B032	-2.7	8.3	2.63	12.098	141	-2.1	30.2	1.40
B034	-2.7	7.9	2.62	11.439	157	-1.1	29.5	0.32
B035	-1.6	8.6	2.62	11.668	141	0.7	26.9	0.61
B036	-4.5	7.3	2.61	11.995	162	1.6	25.3	1.67
B038	-3.5	8.7	2.66	12.404	131	1.1	26.1	0.73
B040	-1.0	9.1	2.66	12.284	127	-1.7	28.8	1.47
B044	-2.6	8.8	2.60	11.358	141	0.8	26.4	0.89
B047	-5.0	8.2	2.60	11.993	144	-1.4	29.5	1.07
B048	-1.7	9.9	2.50	11.257	126	-1.7	28.0	0.33