



Thanks Ranchu32 !!!

The R8 50k/33k or 25k potentiometer before soldering set it at approx 80% measured between center leg and GND.
The R12 bias potentiometer before soldering set at max 1k value.

