


SW3 SW2 SW1

2

1



Krell HTS
Main Voltage Select






SW3 SW2 SW1

2


1





Config. No 3




Config. No 4








Config. No 5




Krell HTS
Main Voltage Select




Config. No 6






	SW3	SW2	SW1
2			
1			

[illegible]

Torodial Transformer - Primary Windings and DC Resistances



Diagrams created by www.tiefbassuebertragung.de

