



acquired: 23:08:29 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				


Liberty Audiosuite

printed: 21:43:35 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				


acquired: 23:12:31 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				


Liberty Audiosuite

printed: 21:48:33 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				


acquired: 23:22:36 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				

Liberty Audiosuite

printed: 21:53:06 7/16/2000



2:SIZE	3:RATE	4:INPUT	5:MKR1	6:MKR2	7:WINDOW	8:GAIN	9:DLAY	M7.500	C7.500	0-9.00
25cy	opt	PROBE			BLACKMN	1.0000				