

# Service Information

88-02-25

CDM-2/0500

A88-118

PRODUCT SERVICE GROUP CE AUDIO

## CDM-2/0503

If a CDM-2/0503 has to be replaced, 4822 691 30204 has to be mounted instead of 4822 691 30193. 4822 691 30193 represents CDM-2/0501 with short legs and with a turntable for mechanical disc hold-down. This CDM version is a substitute for a defective CDM-2/0500 or CDM-2/0501.

CDM-2/0503 has been equipped with a turntable with a magnetic disc hold-down. To distinguish the different versions the white sticker on the CDM mentions:

- 3104 102 0500x for CDM-2/0500
- 3104 102 0501x for CDM-2/0501
- 3104 102 0503x for CDM-2/0503

The reason for this action is that the production of the 0503 has been insufficient.

## CDM4 MECHANISMS TO REPLACE CDM2

Service will supply CDM4 mechanisms instead of the existing CMD2 ones.

The main differences between CDM4 and CDM2 are:

1. New radial motor
2. New focus motor
3. No longer selected laser diodes

These differences require electrical adaptations.

Code numbers for replacements:

Old codenr.	New codenr.
4822 691 30193	4822 691 20464
4822 691 30204	4822 691 30205

CDM-4 information and information of adaptations have been added to the manual of the sets.