


**PRINTED CIRCUIT BOARDS**


**Lead-free Solder**


When soldering, use the Lead-free Solder (Sn-Ag-Cu).

MAIN (A SIDE)



MAIN (B SIDE)





SCHEMATIC DIAGRAMS (4/4)  
04-MAIN2