




---

Secondary windings connected in series. You get 600 ohms across orange and black.



---

Secondary windings connected in parallel. You get 66 ohms



---

Secondary windings connected in parallel. You get 300 ohms.

