

Service Bulletin

Harman Kardon Incorporated
55 Ames Court
Plainview, N.Y. 11803
(516) 681-4000

SERVICE BULLETIN #208

MAY 1978

TO: ALL AUTHORIZED WARRANTY STATIONS
FROM: LEN GAYNOR, DIRECTOR OF SERVICE OPERATIONS
SUBJECT: CITATION 16A - TIME DELAY RELAY

Early production versions of the Citation 16A incorporated a Relay Board Assembly #00132979 which performed two functions. One was a time delay at initial turn on of the amplifier and the other was a DC sensing circuit to turn off the amplifier when DC was present at the output.

There have been a small number of instances where the relay has become defective because of the DC sensing circuit.

We recommend that when replacing the relay HK #13031208, the DC sensing circuit be disabled. This can be accomplished by clipping out resistor R4 (47 ohms) on the Relay board.

Sincerely,



Len Gaynor
Director of Service Operations

LG:an

4/20/78