

C O M P L E T E S E R V I C E B U L L E T I N I N F O

=====TIS200C=
PAGE : 01/01

Reference number : HIFI00178

Subject : CIRCUIT CHANGE IN POWER SUPPLY

Date : 13/02/78

Appl. model(s) : TA5650

=====

IN LATEST SERIES OF THIS MODEL, THE POWER SUPPLY CIRCUIT HAS SLIGHTLY BEEN MODIFIED BY ADDING FIELD EFFECT TRANSISTOR 2SK422 (Q409). CONSEQUENTLY, ALSO THE MOUNTED CIRCUIT BOARD HAS SLIGHTLY BEEN MODIFIED. MODIFICATION OF THE OLDER UNITS IS NOT NECESSARY.

=====

CLEAR	Stop	PF1 Help	PF2	PF3 Back	PF4	PF5	PF6
Cursr Sel		PF7	PF8	PF9	PF10	PF11	PF12 Menu

S ■

Aa

FX

SONY SERVICE CENTRE EUROPE NV

TECHNICAL INFORMATION SERVICE

C O M P L E T E S E R V I C E B U L L E T I N I N F O

=====TIS200C=
PAGE : 01/02

Reference number : HIFI00878

Subject : V-FET SERVICE KITS

Date : 29/04/78

Appl. model(s) : TA5650 , TA4650 , TA8650 , TAN8550

=====

PLEASE NOTE THE AVAILABILITY FROM NOW ON OF THE FOLLOWING KITS OF N-CHANNEL AND V-CHANNEL V-FET'S. ALL V-FET'S PER KIT WILL BE MATCHED, RANKS OF THE KITS THEMSELVES MAY VARY BETWEEN 4 AND 7.

DESCRIPTION : 2 PCS V-FET KIT, CONTAINS 1 X 2SK60, 1 X 2SJ18 -
PN X48392051 - USED FOR TA4650 - PRICE N / 4 PCS V-FET KIT - 2 X 2SK60,
2 X 2SJ18 - X48407051 - TA5650, TAN5550 - PRICE R / 6 PCS V-FET KIT -
3 X 2SK60, 3 X 2SJ18 - X37010461 - TA8650, TAF7B, TAN8550, TAN7B -
PRICE U.

NOTE : IF ONLY PART OF THE V-FET'S IN A SET IS FOUND DEFECTIVE, YOU CAN KEEP THE GOOD ONES IN STOCK AND MATCH THEIR RANKS WITH SOME FROM ANOTHER

=====

CLEAR	Stop	PF1 Help	PF2	PF3 Back	PF4	PF5	PF6
Cursr Sel		PF7	PF8 Next	PF9	PF10	PF11	PF12 Menu

S ■

Aa

FX

SONY SERVICE CENTRE EUROPE NV

TECHNICAL INFORMATION SERVICE

C O M P L E T E S E R V I C E B U L L E T I N I N F O

=====TIS200C=
PAGE : 02/02

Reference number : HIFI00878

Subject : V-FET SERVICE KITS

Date : 29/04/78

Appl. model(s) : TA5650 , TA4650 , TA8650 , TAN8550

=====

SET FOR FURTHER USE.