



Adjust P2/ R7 and P3/ R13  
to 180 Ohm  
ground gate of T1-T4  
lift point A from ground  
adjust A to ground to 0V  
wire the circuit back  
adjust DC offset after T7 / T8  
to + - 5mV with P2  
fine adjust Offset with P4  
OP1, OP2, OP3 decoupled  
with 220uF, 1u, 10n  
T1 / T2 = 2SK170BL  
T3 / T4 = 2SJ74  
T5 / T8 = BF446A  
T7 / T8 : selected for Hfe  
OP1 = LME49710  
OP2 = OPA134