

R1 18.94 - 18.91
R2 18.9 - 8.96
R3 9.1 - 0
R4 18.71 - 1.77

R 100 0-0

R 101 0-0

R 102 0-0

R 103 9.31 - 8.47

R 104 .002 - .001

R 105 .002 - 0

D1 18.9 - 8.9

D2 1.76 - 0

C1 18.9 - 0

C2 7.35 - 0

C3 18.9 - 0

C 101 9.28 - .001

L #1 1W 0

R #1 1W 0

L #2 1W .002

R #2 1W 0

L out 0 R out .025

Q100 .056
.014
.015

Q101 .019
.004
.003

Q 200
.037
.002
.000

Q201
.002
.002
.002

R200 0-0

R201 0-0

R 202 0-0

R 203 9.36 - 1.11

R 204 0-0

R 205 0-0

C201 5.95 - 0