

<b>COMPONENT Model #</b>	<b>L300 S/N 17574</b>		<b>L300 S/N 17577</b>	
	S/N	Condition	S/N	Condition
077 Hi-Frequency Radiator	72573	Excellent	71796	Excellent
LE85 Compression Driver	48022	Excellent	48017	Excellent
H92 Horn	9734	Excellent	9704	Excellent
N333 Network (crossover)	7224	see note 1	7217	Excellent
L91 Diffuser	missing	n/a	67709	see note 2
136A Low-Frequency Transducer	23603	see note 3	23601	Good

Note 1. Minor water damage to lower 1" outside of network component box. No internal damage.

Note 2. Minor chip on outer corner of one fin. Needs re-gluing in 3 places.

Note 3. Needs surround replaced. Minor corrosion of frame's lower 3" from contact with wet cabinet.

Note 4. Needs surround replaced.