


Across R11 and R10 measure 450mV \pm 50mV

Across R16 and R17 measure 375mV \pm 50mV

Copyright Andrew C. Russe
2018. Strictly For DIY Perso
Only. All rights Reserv

+26~28V

FUSES ARE 5A 5X20MM SLOW BLOW



measured on $t=0$