


Jan. 26, 1994



Accordingly mis alignment of the left and right position of the lead wire may expose the lead part. Although this will not present any problem in its reliability consideration toward lead exposure should be given in the designing.

The dimension between the lead shows the resin root dimension.

*Lead wire dimension. (The bottom of lead)