


DIAGRAM A

331, 332, 333
334, 335, 336



DC OFFSET ADJUSTMENT (after 2 hour warm up)
Using DC voltage meter, measure across the (+) and
(-) output terminals, and adjust VR1 for >10mV.