


VR2



85.26

OUTPUT BIAS ADJUSTMENT (after 2 hour warm up)
Using a DC voltage meter, measure from point A to point B and adjust VR4 for 45mV.