



13. Unless the VT1000 is allowed sufficient time to cool down after this type of test, it will terminate testing early and “Fail” the tube; as can be seen in the following data charts for a fresh “matched” EL34. So, the VT1000 can’t be conveniently “tricked” into “rating” power tubes at a higher cathode current!