



Not Recommended for New Design: DS2 Series Relays

NRFND.PG0001.10.9.2020

10.9.2020

About This Notice:	The DS2 Series Relays are Not Recommended For New Design due to future plans for discontinuation.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See Attached. Includes all custom products. There are no direct replacements.
Datasheet(s):	See Attached.
Notes:	DS1 Series Relays are not included in this Notice and remain active.