



A

B

C

D

SOLDER MASK BOTTOM



JUMPER CONNECTIONS – BOTTOM SIDE

Connect jumpers as shown when placed on the BOTTOM side of a one-sided PWB. Use AWG #30 or #28 insulated wire. Install jumpers in drilled-through VIA's. (Pad sizes exaggerated for clarity; component mounting holes shown for reference only.)

Title SW-OPA DISC OPAMP SMT(1) PWB		
Size	Number SWOPA2620PWB1	Rev A
Date	Fri Jan 25, 2013	Drawn by D. Chisholm
File Name	SW-OPA DISC Opamp01_alt1.pcb	Sheet of

A

B

C

D