

Notice



<input type="checkbox"/> CORRECTION	<input type="checkbox"/> PRODUCTION CHANGE
<input type="checkbox"/> SERVICE FLASH	<input checked="" type="checkbox"/> ADD INFORMATION
<input type="checkbox"/>	<input type="checkbox"/>

FILE NO.

Please add this notice to the Service Manual listed below.

Category : **DVD Player**


Date : **Jan. 2002**

Model : **DVD-9201, 9501, 9501KR, 9501PR**

Destination : **US,CA,SS,KR** Reference No. : **SM5810237**

Issue Number : **1**

(Caution of pick up on DVD base mechanism.)



Before disconnecting FFC cable, make it "SHORT" as shown left.
After connecting FFC cable, make it "OPEN" as shown left.

Prod. Code : 137 108 04 9201(SS)
137 109 04 9501(SS)
137 109 06 9501KR(KR)
137 108 05 9501PR(US)
137 108 06 9501PR(CA)

SANYO Electric Co., Ltd
Osaka Japan