



Pos 1 = 200mV - Gm up to 20

Pos 2 = 2V - Mu up to 2

Pos 3 = 20V - Mu up to 20

NOTE:

Mu of 1 = amplification factor of 1

## SEG.009 True-rms

Designer's name

Rev 1.0

12/10/2007

Page 2/4