

All 1 % resistors metal film or thin film

L1, L2: some sort of high-loss ferrite bead that is used as a base stopper, if required, or a small resistor

