



The exact position of the 5 holes shall
be taken from the chassis

The 3 seatings may be milled off 7/64" (2,8mm) or replaced by battens if required.

