

Distortion

Apply a signal of 1 kHz and drive the amplifier to 12 V on the output terminals when the load is 4 ohms.

- Adjust R163 (left) and R263 (right) to minimum distortion. The distortion should be less than 0.005%.