

$L = L_{res} + \text{Trafo leakage Inductance}$

$F_{res} = 1 / (2 * \pi * \sqrt{L * C})$

