


RTX6001: Mounting Overvoltage Control Circuit

171208

The description is shown for one channel. The modification should be performed on both channels.
Start by removing these two resistors.




Solder the 4 short wires and one long wire on the Main PCB.

Mount the small PCB on top of IC501 (IC401) with double-sided adhesive tape.

Solder the 5 wires to the small PCB.

Secure the long wire with tape on RL501 (RL401) and PCB.



RTX6001: Mounting Overvoltage Control Circuit

171208

