






IC15:  $\mu$ PD4016-CX, LC3517A-15, TMM2015BP,  
TMM2016BP, CXK5816SP, CXK5816PS or  
CXK5816PN  
2048-Word x 8 bit Static RAM



IC16: YM3613B  
Digital Audio Interface Transmitter (DIT)



IC22, 23: PCM56J  
D/A Converter



For Service Manuals Contact  
MAURITRON TECHNICAL SERVICES  
8 Cherry Tree Rd, Chinnor  
Oxon OX9 4QY  
Tel:- 01844-351694 Fax:- 01844-352554  
Email:- enquiries@mauritron.co.uk