

```

K1 L1 L2 L3 0.9999918
.option plotwinsize = 0
.step param A 1 2 1
.INC 6080.inc
.INC 6ej7.inc
.tran 3m

```

