

```

.tran 3m
.step param A 1 2 1
.option plotwinsize = 0
K1 L1 L2 L3 0.99998
.INC 6c19p.inc
.INC 6ej7.inc

```

