

```

.PARAMS F=20K, V=1 FBR=2.21K, CFLT=100pf
.tran 0 5m 0 1E-8
.options plotwinsize=0 ;ac dec 25 .1 100Meg
.FOUR (F) V(OUT)

```

Copyright 2008 - Russ White DIY Use Only

